

KEYED SHEET NOTES

- 1

K/17.5 AND K/22.5  
DESTRUCT. TEST  
LOCATIONS HISTORIC
- 2


GENERAL NOTES


- 1


FOR LCD DESTRUCTIVE TESTING  
LOCATIONS, SEE LOCATION AND  
SAMPLE SUMMARY.
- 2


THE LOCATION OF VAV'S  
(TERMINAL UNITS) IS  
APPROXIMATE


LEGEND


- 


CURRENT WATER STAINED  
SURFACE
- 


CURRENT MOLD GROWTH
- 

HISTORIC MOLD GROWTH
- 


HISTORIC WATER LEAK/  
STAINED CEILING TILE
- 


ACTIVE WATER  
LEAK
- 


CURRENT WATER  
ON FLOOR
- 


HISTORIC WATER  
ON FLOOR
- 


DESTRUCTIVE TESTING  
LOCATION (HISTORIC)
- 325

ROOM NUMBER
- 

LCD INSP. LOCATION  
NO FINDINGS
- 

LCD INSP. LOCATION  
ACTIVE LEAK
- 

LCD INSP. LOCATION  
WATER STAIN
- 

LCD INSP. LOCATION  
OTHER NOTATION  
SEE WDA SUMM.
- 

LCD INSP. LOCATION WITH  
MULTIPLE FINDINGS "A",  
"B", OR "C" AS INDICATED



PRIME CONSULTANT



REVISIONS

NO.	DATE	NOTES
1	11/23/08	DRAFT
2	12/14/08	FIELD EDITS
3	12/17/08	FIELD EDITS

CLIENT  
STATE OF CALIFORNIA  
DEPARTMENT OF GENERAL SERVICES

PROJECT LOCATION  
BOARD OF EQUALIZATION  
450 N STREET  
SACRAMENTO, CA. 95814

PROJECT  
STATE OF CALIFORNIA, DGS  
BOE ASSESSMENT

DESCRIPTION  
WATER DAMAGE  
SURVEY

LOCATION  
21ST FLOOR

SHT NO. SHT NAME  
21 A21